

**BLACKFEET COMMUNITY WATER PROJECT**  
**BCWP P1-002      East Glacier Water Line/Tank**  
**Contractor - Chief Construction Specialties, Inc.**

July 11, 2003



This shows one of the normally dry runoff stream crossings. The winter work appears to have held up well.



Another of the dry crossings. The spring runoff did not cause any problems with these crossings.



Another view of a portion of the pipeline. There will be additional excavation with a trencher (Fiberoptic line) before restoration.



There is a bear in this photo, dark object in center behind trees. John was reluctant to go after a close-up.



In Jan and Feb, when this area was excavated, the frost was about 2 ft. deep.

Contractor is to be mobilizing equipment and manpower this weekend and will start work on 15<sup>th</sup>. This will include finishing the Fiberoptic line, all finish work on previously installed main and valves and begin to install the foundations for the water tanks and then the tanks themselves and do the site restoration. Work should be complete by October.